

Pictures taken of project work at:

Llandeilo C.P. School

20 Rhosmaen St
Llandeilo, SA19 6LU
Wales, United Kingdom

Work Tasks:

1. Tiles repaired
2. Tiles re-enamelled in high-gloss white
3. Hand washbasins repaired
4. Hand washbasins re-enamelled in high-gloss white
5. Girls toilet cubicles repaired
6. Girls toilet cubicles re-surfaced in pink fleck granite effect
7. Boys toilet cubicles repaired
8. Boys toilet cubicles re-surfaced in black granite effect
9. All work completed on-site

Completion time: 4 days



Fig1: Drilled holes/cracks in tiles repaired and handbasins repaired and re-enamelled in high-gloss white





Fig2: Toilet cubicles repaired and resurfaced in pink fleck granite effect






Fig3: Cracked tiles, chipped and tired handbasins re-enamelled in high-gloss white





Fig4: Drilled holes and cracks repaired and re-enamelled in high-gloss white





Fig4: Cracked tiles repaired and re-enamelled





Fig6: Before and After





Fig7: Before and After





Fig8: Toilets repaired and cubicles resurfaced in fleck granite effect





Fig9: Before and After





Fig10: Before and After






Fig11: Before and After

